


Трюмо-1

Dressing table-1



Д-830, Ш-380, В-1270, мм.




L-830, W-380, H-1270, mm.

Інструкція збірки
Assembly instruction






«Трюмо-1»/«Dressing table-1»

№	довжина(мм) length(mm)	ширина(мм) width(mm)	кількість quantity
1	830**	380**	1
2	645**	360	1
3	586*	360	1
4	586*	360	1
5	318*	350	1
6	350*	360**	1
7	438**	346**	1
8	450	710	1
9	778*	600**	1




№	довжина(мм) length(mm)	ширина(мм) width(mm)	кількість quantity
10	748*	158**	1
11	100*	120	2
12	460*	300	1
13	615	346	1
14	334*	100	2
15	294*	100	1
16	158**	346**	1
17	292	355	1






1.




2.









3.



4.








5.







5


6.






7.






6



8.

 x1 E16 96mm	 H	 x8 D 3,5x16
 x1 L7 L=350mm	 x2 P	 x4 B3



A=B

