


Трюмо-7

Dressing table-7






Д-1000, Ш-380, В-1300, мм.

L-1000, W-380, H-1300, mm.







Інструкція збірки
Assembly instruction

Трүмо-7/Dressing table-7

№	довжина(мм) length(mm)	ширина(мм) width(mm)	кількість quantity	№	довжина(мм) length(mm)	ширина(мм) width(mm)	кількість quantity
1.	860*	380**	1	11	244*	100	2
2.	1002*	380**	1	12	380*	100	2
3.	424*	380	1	13	262**	207**	2
4.	424*	380	1	14	398**	143**	2
5.	301*	380**	1	15	800**	530**	1
6.	380	150*	1	16	856	172	1
7.	380	150*	1	17	446	298	1
8.	380	150*	1	18	240	355	2
9.	400*	70*	2	19	376	355	2
10	334*	100	8	20	720	470	1






1.








3





2.






3.









4.



5. x4

 E11	 D1 3,5x30	 A2 30mm	 D 3,5x16
 H	 L7 L=350mm	 P	 B3



A=B

